



SOURCE RETURN KIT FOR SPENT OR MISORDERED PRODUCT

CONTENTS FOR YOUR CONVENIENCE:

- 1) F-107 HAZARDOUS MATERIALS Training Warning
- 2) DOT HAZMAT Training Brochure
- 3) F-108 Source Return Packing List Form
- 4) Return Authorization Label with RA number
- 5) Guide 163 Radioactive Material (Low to High Level Radiation)
- 6) Dangerous Goods Labels
 - a. **Limited Quantity**
 - i. UN2910
 - b. **Yellow II – UN2915 (See Note Section)**
- 7) Cargo ONLY Label
- 8) Brown Kraft labels for any necessary box repairs
- 9) Green Dot Label to be applied to outside of box for mis-ordered or defective source returns.
- 10) Fed Ex Airway Bill

Note:

- a) Labels to be applied to package provided by International Isotopes, Inc.



International Isotopes Inc.

- b) If 2915 refer to F-107 - apply Yellow II labels with necessary information.
- c) If replacement box is needed, contact your distributor.

FEDERAL EXPRESS DECLARATION OF DANGEROUS GOODS FORM

You may or may not be required to ship using a Declaration of Dangerous Goods (DG form).

Federal Express requires these forms to be type-written. For an easy to complete form go to:

- A. www.fedex.com/us/service-guide/ship-dg-hazmat/dangerous-goods/
- B. Select "Find Resources", then select "tools to help ship", then select "Declaration Forms".
- C. **Select pdf and complete the declaration form.**

The website also offers information and guidance on the shipment of dangerous goods.